

# i-PRO



## Rack NVR | SR1XL | NVR-R-1 (36TB-60TB)

Model	Total Storage	Usable Storage	RAM	Processor	Power Supply
NVR-R-1-36TB-V8	36TB (3 x 12TB)	24TB	32GB	Single	Dual
NVR-R-1-48TB-V8	48TB (3 x 16TB)	32TB	32GB	Single	Dual
NVR-R-1-60TB-V8	60TB (3 x 20TB)	40TB	32GB	Single	Dual

- To meet total storage, individual HDD size and quantity may be subject to change.
- Total usable storage is calculated based on advertised HDD size, not OS recognition.
- Usable storage size may vary slightly.
- Special order items should allow 14+ business days for delivery.

### Preloaded Network Video Recorder – Rack Server

- VI Software Installed
- VI Server Activation Included
- Includes Ongoing Updates for the Video Insight Edition Installed
- Fully Configured and Tested
- “Plug & Play” NVR is Ready for Out-Of-The-Box Deployment
- Recommended Use Case | 150-300Mbs Recording Rate Performance | 1Gbs Network
- 5-Year Next Business Day On-site Service (After Remote Diagnosis by i-PRO Support Team)
- 1-Year VI HM+ Activation Included (Meant for use on secondary machine)

### Server Specifications

#### Processor

1 x Xeon 6-Core / 12-Thread

#### Memory

32GB

#### I/O Slots

Up to 2 x Gen3 Slots

#### Optical Drive

No

#### RAID Controller

H755

#### iDRAC

iDRAC9 Express

#### Embedded NIC

2 x 1GB Base-T

#### Power Supply

2 x 600 Power Supply

#### Security

On-board Encryption | TPM 2.0

#### Operating System

Windows Server 2025 Standard

#### Accessories

Keyboard and Mouse

#### Graphics Card

Intel Onboard Graphics

#### Video Output

VGA

#### Weight

29 lbs

#### Dimensions

1U Rack Mount: (H)1.69”, (W)18.9”, (D)23.58”

#### HDD Bays

Up to 4 x 3.5” Enterprise Drives (Storage RAID 5)  
OS on 2 x M.2 High Speed SSD Drives (RAID 1)

#### Warranty

5-Year Next Business Day On-site Service (After Remote Diagnosis by i-PRO Support Team)

#### Monitor

Not Included

#### Rails

Rails Included | 4 Post

- Rear drives: If unit supported, are special order and will require extra configuration time.
- Server warranty will not cover issues resulting from third-party parts.
- Hardware meets NDAA standards.

